



VEHICLE PPSR CHECK REPORT

Provided by CheckMyCars — PPSR search result summary

Date: 21 July 2026
Time: 01:33:46 AEDT

This Vehicle PPSR Check Report is provided by CheckMyCars and is based on information obtained from the Personal Property Securities Register (PPSR) and related sources at the time of the search. It is not an official

VEHICLE IDENTIFICATION

VIN: **JTMZD33V80523XXXX**

VEHICLE DETAILS

NEVDIS & Industry Data

IDENTITY	
Registration:	XXX767 (VIC)
Vehicle Type:	Passenger Vehicle
Make:	TOYOTA
Model:	LAND CRUISER 300
Variant:	Sahara
Year of Manufacture:	2022
Body Type:	Wagon
Colour:	White

ENGINE & DRIVETRAIN	
Engine Number:	1GRFE1234567
Engine:	3.5L V6 Twin Turbo (6 cyl)
Transmission:	10 Speed Automatic
Fuel:	Petrol
Drive:	Four Wheel Drive
Power:	305 kW / 650 Nm

DIMENSIONS & FEATURES	
Doors:	5
Seats:	7
Kerb Weight:	2670 kg
Dimensions:	4985L x 1990W x 1920H mm
Driver Side:	Right
Immobiliser:	Yes

PRICING	
New Car Price (RRP):	\$131,000

PPSR SEARCH RESULTS

✓ **SECURITY INTERESTS: NONE FOUND**

No finance or security interests registered on the PPSR.

✓ **WRITTEN-OFF STATUS: NOT WRITTEN OFF**

No written-off notifications found in NEVDIS.

✓ **STOLEN STATUS: NOT REPORTED STOLEN**

This vehicle has not been reported stolen.

MARKET VALUATION

Confidence: 78%

Valuing: 2022 Toyota Land Cruiser 300 Sahara GR Petrol Auto

Estimated Retail Price

\$125,000

Range: \$118,000 — \$132,000

Estimated Kilometres: 35,000 km

Estimated Trade Price

\$110,000

Range: \$105,000 — \$115,000

Valuations are indicative estimates and should not be solely relied upon for purchase decisions.

MARKET DATA VEHICLE SPECS

Badge: Sahara · Model Year: MY22 · Release: 01/2022 · Engine Type: Piston

CLAIM REPAIR HISTORY

Insurance Claim Records

Claims Search Vehicle: 2022 Toyota Land Cruiser 300 | VIN: JTMZD33V80523XXXX | Plate: XXX767 (VIC)

■ **2 CLAIMS FOUND**

Total estimated repair cost: A\$15,500 – A\$16,500 AUD

Claim 1 — Jun 2023


A\$3,000 – A\$3,500 AUD

Damage Areas:


- Exterior body parts
- External lighting

Damage Positions:

- 02: Front, Left side, Middle
- 08: Front, Middle, Middle



TOP VIEW



FRONT VIEW


● Damaged Zone

Claim 2 — Jul 2024


A\$12,500 – A\$13,000 AUD

- Damage Areas:
- Exterior body parts
 - Suspension system


- Damage Positions:
- 13: Middle, Right side, Top
 - 14: Middle, Right side, Middle
 - 23: Rear, Right side, Middle



RIGHT SIDE VIEW



TOP VIEW



REAR VIEW

● Damaged Zone

Note: Vehicle images shown are generic illustrations for reference only and do not represent the actual vehicle. Damage positions are approximate and based on claim data provided.

Important: This data is sourced from industry partners and may not include all insurance repair records. Information is based on repair quotations and does not confirm whether repairs were approved or completed. The absence of records does not guarantee a claim-free history. Always inspect the vehicle and verify with the seller.

MARKETPLACE LISTING HISTORY

When (AEST/AEDT)	Event	Marketplace	Seller	Odo (km)	Price
02/05/2024 09:30 AEST	listing	Marketplace list	dealer	43,800	\$26,800
18/05/2024 11:00 AEST	price change	Marketplace list	dealer	44,150	\$25,990
05/06/2024 16:20 AEST	price change	Marketplace list	dealer	44,300	\$24,900
28/06/2024 08:45 AEST	delisting	Marketplace list	dealer	44,300	\$24,900

OFFICIAL PPSR SEARCH CERTIFICATE

The official PPSR Search Certificate has been attached to your email as a separate PDF.

PPSR Search Number: PPSR-TEST-2026-001

You can also download it from your report page at www.checkmycars.com.au

ANCAP SAFETY RATING

★★★★★ (5/5 Stars)
Adult: 89% | Child: 87% | Pedestrian: 79% | Safety Assist: 82%
Tested: 2022 | Vehicle: Toyota Land Cruiser 300

VEHICLE RECALLS Source: NHTSA

1 RECALL FOUND

US-sourced NHTSA data. Contact your local dealer to confirm Australian applicability.

NHTSA-2023-001

Air Bags

View on NHTSA →

Certain vehicles equipped with air bags may have a defect in the inflator module.

SAMPLE REPORT — ILLUSTRATIVE ONLY
Fictional vehicle data for demonstration. Your paid report uses live PPSR and partner data.

Important Information

- This report is valid for 1 day from the search date. Download links and data may expire after this period.
- A clear PPSR search does not guarantee that the vehicle is free from all encumbrances.
- You should conduct additional due diligence before purchasing any vehicle.
- PPSR Search Reference: PPSR-TEST-2026-001 - use this to verify the search at www.ppsr.gov.au

Important Information: The accuracy of this report depends on the correctness of the information provided by the user (e.g., VIN) and the data available from the Personal Property Securities Register (PPSR) and other third-party sources at the time of the search. CheckMyCars is not responsible for errors or omissions in the source data. Information may change after the date and time of this report. NEVDIS data, if displayed, is sourced from the National Exchange of Vehicle and Driver Information System and is subject to its own terms and conditions.